



A




2x

B



1x

C




1x

D




1x

O




5x

Ⓖ




2x

Ⓕ




2x

Ⓖ




2x

Ⓖ



2x

Ⓖ




2x

Ⓖ




2x

Ⓖ




2x

E




4x

F




4x

J




2x

O




3x






1 x 56




M6x40mm

2 x 12



M6x20mm

3 x 8



M6x80mm

4 x 80




Washers

5 x 2






4 mm


6 x 4



M6x35mm


1

2 x 8	4 x 8	5 x 1
		
M6x20mm		4 mm




IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.




2

2 x 4	4 x 4	5 x 1
		
M6x20mm		4 mm





IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.





3



IMPORTANT NOTE:





Do not tighten all screws/bolts until all completely assembled.
Thank you.




4




5

1 x 1  M6x40mm	3 x 1  M6x80mm	4 x 2 	5 x 1  4 mm
---	---	--	--








IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.




6

1 x 1  M6x40mm	3 x 1  M6x80mm	4 x 2 	5 x 1  4 mm
---	---	--	--







IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.





7

1 x 6  M6x40mm	4 x 6 	5 x 1  4 mm
---	--	--







IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.





8

6 x 2  M6x35mm	4 x 2 	5 x 1  4 mm
---	--	--




IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.



9

1 x 4



M6x40mm


4 x 4



5 x 1



4 mm



80%



IMPORTANT NOTE:



Do not tighten all screws/bolts until all completely assembled.
Thank you.

10

5 x 1



4 mm




x16

5

100%




100%



IMPORTANT NOTE:





Do not tighten all screws/bolts until all completely assembled.
Thank you.



11



x2


12

1 x 1  M6x40mm	3 x 1  M6x80mm	4 x 2 	5 x 1  4 mm
---	---	--	--









IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.



13

1 x 1  M6x40mm	3 x 1  M6x80mm	4 x 2 	5 x 1  4 mm
---	---	--	--



IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.

14

1 x 7



M6x40mm


4 x 7




5 x 1



4 mm



80%



IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.

15

1 x 7



M6x40mm


4 x 7




5 x 1



4 mm







80%



IMPORTANT NOTE:


Do not tighten all screws/bolts until all completely assembled.
Thank you.

16




IMPORTANT NOTE:

Do not tighten all screws/bolts until all completely assembled.
Thank you.



17



x2

MERKURY MARKET
spółka z ograniczoną odpowiedzialnością sp.k
ul. Czajkowskiego 51
38-400 Krosno Poland
bok@merkurymarket.pl
Art. No. 8039711
PO#: 402352